



ACCESSORY FOR SWITCH DISCONNECTOR W/FUSE,  
IN-LINE, PLUG-IN, AMPEREMETER,  
MOVING IRON 500/1A, CL.1,  
0.6 VA DOUBLE OVERLOAD

Similar to image

### Technical data:

|                                 |  |                      |
|---------------------------------|--|----------------------|
| Design type                     |  | -                    |
| Type, explanations              |  | -                    |
| Type, explanations additionally |  | -                    |
| Accessories                     |  | Ammeter, moving-iron |

### Certificates/approvals:

|                          |     |
|--------------------------|-----|
| General Product Approval | EMC |
|--------------------------|-----|



### Further information:

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.com/lowvoltage/catalogs>

Industry Mall (Online ordering system)

<http://www.siemens.com/lowvoltage/mall>

Service&Support (Manuals, Certificates, Characteristics, FAQs,...)

<http://support.automation.siemens.com/WW/view/en/3NJ6900-4HK11/all>

Image database (product images, 2D dimension drawings, 3D models, device circuit diagrams, ...)

[http://www.automation.siemens.com/bilddb/cax\\_en.aspx?mlfb=3NJ6900-4HK11](http://www.automation.siemens.com/bilddb/cax_en.aspx?mlfb=3NJ6900-4HK11)

**last change:**

Feb 14, 2013