



FUSE-SWITCH-DISCONNECTOR FOR SURFACE MOUNTING AND FOR INSTALLATION 3-POLE, I=400A, U=400/500V AC AUXILIARY SWITCH 1NO+1NC FUSE SIZE NH1 AND NH2 WITH FLAT PAD CONNECTION G WITH FITTED EFM, INTERNAL POWER SUPPLY (INCLUDING CONTROL CABLE 1M) AUXILIARY SWITCH 2NO+1NC

Figure similar

Certificates

Declaration of Conformity	Test Certificates	other	
 EG-Konf.	spezielle Prüfbescheinigungen	Bestätigungen	sonstig

Further information

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.com/lowvoltage/catalogs>

Industry Mall (Online ordering system)

<https://eb.automation.siemens.com/mall/en/WW/Catalog/Product/3NP5360-0HA13-Z R01>

Service&Support (Manuals, Certificates, Characteristics, FAQs,...)

<http://support.automation.siemens.com/WW/view/en/3NP5360-0HA13-Z R01/all>

Image database (product images, 2D dimension drawings, 3D models, device circuit diagrams, ...)

http://www.automation.siemens.com/bilddb/cax_en.aspx?mlfb=3NP5360-0HA13-Z R01

CAX-Online-Generator

<http://www.siemens.com/cax>

