SIEMENS

Product data sheet 3RS1041-1GW50



TEMPERATURE MONITORING RELAY PT100/1000, KTY83/84, NTC 3 SENSORS, 2 THR. VAL., DIGITAL -50 DEG. C TO 500 DEG. C 24-240V AC/DC 2 X 1 W + 1 NO, WIDTH 45 MM SCREW CONNECTION

General technical details:				
Type of voltage		AC/DC		
Supply voltage frequency				
 1 / for auxiliary and control current circuit 				
• initial rated value	Hz	50		
• final rated value	Hz	60		
• 1 / at 50 Hz / for AC / initial rated value	V	24		
• 1 / at 50 Hz / for AC / final rated value	V	240		
• 1 / at 60 Hz / for AC / initial rated value	V	24		
• 1 / at 60 Hz / for AC / final rated value	V	240		
• 1 / for DC / initial rated value	V	24		
• 1 / for DC / final rated value	V	240		
Number of measuring circuits		3		
Product function				
defect storage		Yes		
• reset external		Yes		
Measurable temperature				
• initial value	°C	-50		
• final value	°C	500		
Reference code / according to DIN EN 61346-2		К		

Reference code / according to DIN 40719 extended according to IEC 204-2 / according to IEC 750		К
Ambient temperature		
during operating	°C	-25 +60

Mechanical design:				
Design of the electrical connection				
for auxiliary and control current circuit		screw-type terminals		
• jumper socket		Yes		
Design of the sensor / connectable		PT100/1000, KTY83/84, NTC (resistance sensors)		
Number of NC contacts / for auxiliary contacts		0		
Number of NO contacts / for auxiliary contacts		1		
Number of changeover contacts / for auxiliary contacts		2		
Width	mm	45		
Height	mm	106		
Depth	mm	91		

Certificates/approvals:

General Product Approval







Test Certificates

Special Test Certificate Declaration of Conformity

other

 $\frac{\text{Environmental}}{\text{Confirmations}}$

Further information:

Information- and Downloadcenter (Catalogs, Brochures,...)

http://www.siemens.com/industrial-controls/catalogs

Industry Mall (Online ordering system)

http://www.siemens.com/industrial-controls/mall

Cax online generator:


http://www.siemens.com/cax


Service&Support (Manuals, Certificates, Characteristics, FAQs,...)

http://support.automation.siemens.com/WW/view/en/3RS1041-1GW50/all

Image database (product images, 2D dimension drawings, 3D models, device circuit diagrams, ...)

http://www.automation.siemens.com/bilddb/cax_en.aspx?mlfb=3RS1041-1GW50





last change: Jul 28, 2014