


SPARE CONTACTS F. SIZE S10 F. CONTACTOR
3RT1064,110KW/AC-3 CONSISTS OF 3 MOVABLE AND 6
FIXED CONTACTS WITH FIXING PARTS



Certificates/ approvals:

Declaration of
Conformity

Test Certificates



[Special Test
Certificate](#)

Shipping Approval



Shipping Approval

other



[other](#)

[Environmental
Confirmations](#)

Further information:

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.com/industrial-controls/catalogs>

Industry Mall (Online ordering system)

<http://www.siemens.com/industrial-controls/mall>

Cax online generator

<http://www.siemens.com/cax>

Service&Support (Manuals, Certificates, Characteristics, FAQs,...)

<http://support.automation.siemens.com/WW/view/en/3RT1964-6A/all>

Image database (product images, 2D dimension drawings, 3D models, device circuit diagrams, ...)

http://www.automation.siemens.com/bilddb/cax_en.aspx?mlfb=3RT1964-6A

last change: