

SHUNT TRIP UNIT 220...240V AC,
220...250V DC FOR FRAME SIZE 3RV1. 6,
7, 8

Certificates/approvals:

Declaration of Conformity	Test Certificates	Shipping Approval	
 EG-Konf.	Special Test Certificate	 BUREAU VERITAS	 RMRS
other			
Confirmation	Declaration of Conformity	other	Environmental Confirmations

Further information:

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.com/industrial-controls/catalogs>

Industry Mall (Online ordering system)

<http://www.siemens.com/industrial-controls/mall>

CAX-Online-Generator


<http://www.siemens.com/cax>

Service&Support (Manuals, Certificates, Characteristics, FAQs,...)

<http://support.automation.siemens.com/WW/view/en/3RV1982-1EF0/all>

Image database (product images, 2D dimension drawings, 3D models, device circuit diagrams, ...)

http://www.automation.siemens.com/bilddb/cax_en.aspx?mlfb=3RV1982-1EF0



- S0 OFF button in the plant
- Q1 Motor starter protector
- S Auxiliary switch of the molded case motor starter protector Q1
- F1, F2 Fuse (gL/gG), max. 10 A
- F3 Shunt trip unit

last change: