

SITRANS P DS III, HART, 4-20 MA transmitter for absolute pressure from pressure transmitter series Measuring cell filling silicone oil, normal cleaning Span: 1 to 30 bar a (14.5 to 435 psi a), overload limit 100 bar Diaphragm stainless steel measuring cell stainless steel Process connection: connection shank G1/2 B to EN 837-1 Die-cast aluminium housing International design english inscription an documentation as cd None explosion protection Electric connection and cable inlet: cable gland 1/2-14 npt without visible digital indicator (digital display hidden, setting: mA)

Further information

Industry Online Support (Manuals, Catalogs, Certificates, FAQ, ...)
<https://support.industry.siemens.com/cs/products?mfn=ps&lc=en-WW>
Industry Mall (Online ordering system)
<https://mall.industry.siemens.com>

