

E30007




Screw-in adapter for process sensors

PA Adapt PX G1/4A-G1/4A

Status Archive

/E30143



Mechanical data		
Weight	[g]	45.2
Materials	Adapter: stainless steel (1.4305 / 303); Gasket: FKM	
Sensor connection	G 1/4	
Process connection	G 1/4	
Remarks		
Notes	discontinued article	
Pack quantity	1 pcs.	

Status Archive

/E30143