


VW3A9312

substitution kit for ATV38/58 - compatible with
ATV61/ATV71



Main

Accessory / separate part category	Adaptation accessory
Accessory / separate part type	Adaptor
Product compatibility	ATV71HD37Y...HD90Y ATV71HD37N4...HD75N4 ATV71HD18M3X...HD37M3X ATV61HD37Y...HD90Y ATV61HD37N4...HD75N4
Accessory / separate part destination	Variable speed drive
Range compatibility	Altivar 61 Altivar 71
Product specific application	Substitution of an ATV38HD46N4X by an ATV61HD37N4 Substitution of an ATV38HD54N4X by an ATV61HD45N4 Substitution of an ATV38HD64N4X by an ATV61HD55N4 Substitution of an ATV38HD79N4X by an ATV61HD75N4 Substitution of ATV58HD28M2X...HD46M2X by ATV71HD22M3X...HD37M3X Substitution of an ATV58HD28M2X by an ATV71HD18M3X Substitution of an ATV58HD33M2X by an ATV71HD22M3X Substitution of ATV58HD33N4...HD79N4 by ATV61HD37Y...HD90Y Substitution of ATV58HD33N4...HD79N4 by ATV71HD37Y...HD90Y Substitution of ATV58HD54N4...HD79N4 by ATV71HD37N4...HD55N4 Substitution of ATV58HD54N4...HD79N4 by ATV71HD45N4...HD75N4 Substitution of an ATV38HD46N4 by an ATV61HD37N4 Substitution of an ATV38HD54N4 by an ATV61HD45N4 Substitution of an ATV38HD64N4 by an ATV61HD55N4 Substitution of an ATV38HD79N4 by an ATV61HD75N4

The information provided in this documentation contains general descriptions and/or technical characteristics of the performance of the products contained herein. This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither Schneider Electric Industries SAS nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein.